

"RED E. REPAIR"
SAYS:

EXPERIENCE IS
STILL THE
BEST TEACHER!




When **YOU** Have Had
the Experience of
a Repair by **METAL
LOCKING**, You'll Know
Whom to Call When
You Are Next in Trouble.

The increasing number of customers, who consistently return for assistance, tells our **PERFORMANCE STORY**. They know dependability when it comes to permanent repairs.
Let **YOUR OWN EXPERIENCE** be the measure of our ability.

NO REPLACEMENT HERE!



4 CTV. BOREL
BLOCK SHOWS INNER
WATER JACKET
WALL REPAIRED.
CRACK BARE 14"
LONG FROM BLOCK
SURFACE TO BOTTOM
SLEEVE BOREL.
WINDOW SECTION
8'-0" WAS
REMOVED TO
EXPOSE REPAIR AREA.



WINDOW
SECTION HAS
BEEN
REPAIRED.
BOTH WATER
JACKET AND
OIL CHAMBERS
ARE PRESSURE-
PROOF. THIS
REPAIR SAVED
EXPENSIVE
REPLACEMENT
COST.

Metal Locking Service, Inc.

TA 4-4359

•

68 HAYES PLACE, BUFFALO 10, N. Y.

•

TA 4-4359

"NO REPAIR IS BETTER THAN ITS PERFORMANCE"